


D0 STT Crate Power Supply Load Wiring

Eric Hazen – 4 Apr 2004

Boston University <hazen@bu.edu>


Notes:

1. Control wiring ensures proper sequence (3.3V first then 5V on)
2. Each crate and it's supplies should be grounded at one point only




5V PS

3.3V PS



Ground jumper at power supply should be removed



Ground straps from crates- remove all but 1 (see drawing)